



# KENWOOD

ASB-1022

## Service Bulletin

Amateur Radio Division

**Subject:** MC-44/MC-44DM Intermittent Modulation**Date:** May 18, 1993**Symptom:**

Microphone audio is mechanically intermittent., i.e. striking the microphone will cause audio to be lost or restored.

**Cause:**

The lead wire of capacitor C8 might be shorting out against the case of the ECM unit.

**Corrective Action:**

Re-install the capacitor so that the leads cannot touch the ECM case.

